


Front View




Loose/broken/delaminated

Damage/wear/hole

Previous repair

Replaced piece

Rear View




Missing

Spindles not original to desk

Add-ons

Inscriptions

Right Side




■ Loose/broken/delaminated

■ Previous repair

■ Damage/wear/hole

■ Replaced piece

Left Side




■ Missing

■ Add-ons


■ Spindles not original to desk

■ Inscriptions

Top



Bottom




Loose/broken/delaminated

Damage/wear/hole

Previous repair

Replaced piece

Bottom




Missing

Spindles not original to desk


Add-ons

Inscriptions

Drawer Front, Outer Surface



Rear Surface of Drawer Front



■ Loose/broken/delaminated

■ Damage/wear/hole

■ Previous repair

■ Replaced piece

■ Missing



■ Spindles not original to desk

■ Add-ons

■ Inscriptions

Inside Surface of Left Drawer Side

Inside Surface of Right Drawer Side



■ Loose/broken/delaminated

■ Previous repair

■ Missing

■ Add-ons

■ Damage/wear/hole

■ Replaced piece








■ Spindles not original to desk

■ Inscriptions

Rear Surface of Drawer Back





Front Surface of Drawer Back

 Loose/broken/delaminated Damage/wear/hole Previous repair Replaced piece Missing Spindles not original to desk Add-ons Inscriptions



Upper Surface of Drawer Bottom

Lower Surface of Drawer Bottom



■ Loose/broken/delaminated

■ Previous repair

■ Missing

■ Add-ons

■ Damage/wear/hole

■ Replaced piece

■ Spindles not original to desk

■ Inscriptions



Outside Surface, Right Drawer Side

Outside Surface, Left Drawer Side



■ Loose/broken/delaminated

■ Previous repair

■ Missing

■ Add-ons

■ Damage/wear/hole

■ Replaced piece

■ Spindles not original to desk

■ Inscriptions